



One Monarch Drive
Suite 101
Littleton, MA 01460

www.geotransinc.com

978-952-0120 FAX 978-952-0122

Via E-Mail

P.N. 117-3008059

June 16, 2010

Joseph F. LeMay, P.E.
Office of Site Remediation & Restoration
USEPA Region 1
5 Post Office Square Suite 100
Boston, MA 02109-3912

RE: Proposed Relocation of Vapor Intrusion Assessment Well UG8, Wells G&H Superfund Site

Dear. Mr. LeMay:

As indicated to you in a voice mail last week from Tim Cosgrave, field conditions necessitate relocating monitoring well UG8, which is being installed as part of the Vapor Intrusion Assessment. The original location for monitoring well UG8 is proximate to a storm drain catch basin. On June 7, 2010, during the process of clearing the upper six feet for utilities at location UG8, water was observed at a depth of approximately three feet below ground surface. The area was affected by heavy rains the previous day and field observations suggest that this location was likely being affected by leakage from the nearby storm water system. Therefore, we propose to install monitoring well UG8 to the east, adjacent to the building located at 21 Olympia Avenue, and south of existing monitoring well S6. The attached figure shows the proposed change in location for monitoring well UG8.


Please contact Tim Cosgrave or Clayton Smith if you have any questions.

Sincerely,

Anne B. Sheehan
Project Manager

CC: J. Coyne
D. Sullivan
T. Cosgrave
C. Smith
J. Guswa


G:\GRACE CENTRAL\2010\06-10-RELOCATE-UG8\Fig-1-UG8-PRO-WELL.DWG



EXPLANATION

- APPROXIMATE PROPERTY BOUNDARIES DEWEY AVE. NEIGHBORHOOD
- RECOVERY WELL LOCATION
- MONITORING WELL LOCATION
- PROPOSED VAPOR INTRUSION ASSESSMENT PLAN WATER TABLE MONITORING WELL

0 180
Scale in feet

TITLE: WELL LOCATION MAP			
MONITORING WELLS FOR VI ASSESSMENT			
LOCATION: Wells G & H, Woburn, MA.			
		APPROVED	JRB
		DRAFTED	RMK
		PROJECT#	117-3008051-09
		DATE	JUNE 2010
FIGURE			1